


LEGEND

- CG001/CG002
 - Adjacent Site
 - Approximate Location of Former Feature
 - Structure
 - Airfield or Road
 - Buried Tank Area
 - Fuel Tank
 - Fence
 - Main Wastewater Line
 - Service Wastewater Line
 - Abandoned Fuel Line (1952)
 - Abandoned Fuel Line (1962)
 - Former Tank 43 Drain Line
 - Abandoned Fuel Line
 - Main Fuel Line
 - Service Fuel Line
 - 2002 Bioventing Air Injection Line
 - 2004 Bioventing Air Injection Line
 - Index Contour
 - Intermediate Contour Depression
 - Intermediate Contour
 - ¹Proposed Remediation System Optimization Soil Sample
 - Proposed Site Characterization Soil Sample
 - Proposed Site Characterization Soil/Groundwater Sample
 - ¹Bioventing ROI
- Approximate Radius of Influence**

¹See Attachment M-2.



Historical Sample Location

- Hydro Punch
- ⊕ Monitoring Well
- ⊕ Abandoned Monitoring Well
- ⊕ Product Recovery Well
- ⊕ Abandoned Recovery Well
- ⊕ Bioventing System Well
- ⊕ Surface Water Sample
- ⊕ Soil Boring
- ⊕ Surface Soil Sample
- ⊕ Excavation Sample
- ▲ Soil Vapor Sample
- ▲ Vapor Monitoring Point
- ▲ Sediment Sample

**FIGURE D9-CG001/CG002
Proposed Sample Locations**

Work Plan for Site Inspection, Remedial Investigation, and Site Characterization
Former Galena Forward Operating Location, Alaska